



WE 1100-125 / 46614420 / TV 42 / US 120V

Pos.	Part No.	Description	Quant.	Price	Currency abbreviation
1	316085330	Gear housing compl.	1		
2	316040610	Spindle stop compl.	1		
3	141120070	Fill. head screw	3		
4	141123940	Self-tap. fill. h. screw	4		
5	316097810	Flange compl.	1		
6	339013130	Compensating Washer	1		
7	316097550	Bevel gear and pinion	1		
8	143195640	O-ring	1		
9	341166770	Spindle	1		
10	339007790	Washer	1		
11	143193920	O-ring	1		
12	341102660	Hex nut M7	1		
13	143116270	Ball bearing, 8x22x 7	1		
14	141156650	Retaining ring	1		
15	339007940	Washer	1		
16	339153550	Baffle	1		
17	310012760	Armature compl.,110V	1		
18	343392740	Sealing washer	1		
19	143115870	Ball bearing, 6x19x6	1		
20	344114190	Rubber bushing	1		
21	339151290	Baffle	1		
22	314000540	Handle cpl.	1		
23	311014630	Field coil compl.,120V	1		
24	315014750	Motor housing	1		
25	338086730	Rating plate 46614420 WE 1100-125	1		
26	316097610	Brush holder compl.	1		
27	343013510	Carbon Brush 120V	1		
28	141116020	Self-tap fill h screw	1		

